

## BOOTH 6




FIG.5

0.02 0.08 0.04 0.04 0.32 0.40 0.36	HEMFILTER O.123 PRESS	10 RESET NEW	נורובא		DDECCTO	REQUEST	CHANGE			<u>  [2]</u>	122
	PRE HEPA ALARM	95 NO	ON OC					KING.	ACKNOWLEDGE	FILTERCHANGE BOOTH NOT	NG
126B	RE HEF	2148 0.69	000 000					NOT WOR	ACKNC	FILIER	WORKING
9	TIME OPERATOR P	7-1-2003 6:16AM RALPHJAFFKE 02148 0.6995	7.1.2003 2:00PM RALPH JAFFKE 0000 0.000		112			JEST, OR BOOTH	~//  /4	~6//	
F/G. 6	TIME C	6: 16AM	2:00PM	,				rer Real			611/
	DATE	7.1.2003	7.1.2003					EMENT, FIL			
88 126A	STATUS	NISOT	AUTO LOGOUT ( BOOTH OFF)			-129		COMENTS ACKFILTER REPLACEMENT, FILTER REQUEST, OR BOOTH NOT WORKING.	(124 C116	SPRAY BOOTH	NOT WORKING
0.02 0.08 0.04 0.04 0.32 0.40	PRE-FILTER 0-215 128 PRESS	NEW NEW	LILICK (33)	34	DDECC TO	REQUEST   FILTER	CHANGE	130	131	RETURN	10 MAIN




FIG.7